Building Summary Report

For Official Use Only

2010 GSA Tenant Satisfaction Survey

5000 WISSAHICKON AVE, PA0515ZZ

Overall Satisfaction and Indices

			Ve	ry		Ve	ry	%	Change	
		# of	Dissat	isfied		Satis	sfied	Satisfied	from	% Satisfied
Overall Satisfaction		Resp.	1	2	3	4	5	(4, 5)	Previous	(4, 5)
Overall Satisfaction	2010	448	2%	4%	20%	48%	26%	75%	7	75%
	Previous	197	1%	7%	25%	53%	15%	68%		68%

Index Scores		# of Resp.	Mean	Change from Previous	Mean
First Impressions	2010	447	4.22	0.08	4.22
Р	Previous	197	4.14		4.14
Indoor Environment	2010	448	3.25	0.21*	3.25
P	Previous	197	3.04		3.04
Cleaning	2010	448	3.56	0.16*	3.56
	Previous	197	3.40		3.40
Maintenance	2010	448	3.74	0.16*	3.74
P	Previous	197	3.58		3.58
Security	2010	442	4.23	0.19*	4.23
_	Previous	195	4.04		4.04
Elevators	2010	430	3.90	0.04	3.90
P	Previous	188	3.86		3.86
Building Mgmt. Staff	2010	388	4.07	0.22*	4.07
	Previous		3.85		3.85

^{*} Significant change from previous measurement Data shown only if 5 or more cases

2010 GSA Tenant Satisfaction Survey

PA0515ZZ

Individual Items

Admiliant		sfied (4, 5)
Attributes	2010	Previous
First Impressions		
Attractiveness of appearance	85%	85%
Grounds/Landscaping	91%	85%
Attractiveness of common areas/public space	77%	76%
Directional signs	75%	72%
Handicapped accessibility	85%	81%
Indoor Environment		
Ventilation	44%	38%
Temperature, Summer	41%	31%
Temperature, Winter	40%	32%
Quality of indoor air	40%	39%
Restroom ventilation	44%	40%
Noise level	73%	64%
Cleaning		
Elevator cleanliness/appearance	76%	74%
Restroom supplies	51%	48%
Restroom cleanliness	37%	36%
Lobby/Common areas	77%	75%
Work space	60%	55%
Time of cleaning	54%	42%
Maintenance		
Lighting	77%	72%
Restroom Operations/Function	52%	49%
Quality of Building maintenance/upkeep	66%	59%
Quality of Repairs/Service calls	67%	62%
Timeliness of Repairs/Service calls	64%	59%

Data shown only if 5 or more cases

2010 GSA Tenant Satisfaction Survey PA0515ZZ

Individual Items - Continued

	% Satisfied (4, 5)				
Attributes	2010	Previous			
Security					
Security in this building	83%	74%			
Attentiveness of security personnel	83%	79%			
Responsiveness to security questions and issues	86%	78%			
Elevators					
Waiting time	66%	62%			
Dependability	76%	75%			
	80%	80%			
Ride quality	0070				
Building Management Staff					
Accessibility—able to reach	82%	74%			
Courtesy	83%	82%			
Knowledge of building and systems	83%	74%			
Timeliness of response	77%	68%			
Follow-up communication	75%	72%			
Understanding tenant needs/requirements	79%	71%			
Procedures need to go through to get service	76%	66%			
Professionalism	83%	80%			
. Totosoliumom					

Data shown only if 5 or more cases

While you can use and copy this document for official GSA business, including for use with your federal agency customers, it contains proprietary research, copyrighted materials, and literary property of Gallup, Inc. As such, it is not to be copied, quoted, published, or divulged to persons who are not GSA employees or federal agency customers. Instead, it needs to be safeguarded, allowing no one to duplicate or change the contents in an effort to formulate an inferior product. No changes may be made to this document without the express written permission of Gallup, Inc.